

**EXHIBIT 6**

## TECHNICAL ASSISTANCE CENTER

\*\*\*\* GM RESTRICTED \*\*\*\*

<b>Case No:</b>	06957025	<b>VIN:</b>	<div>Privacy</div>
<b>Date Opened:</b>	20031125	<b>Model Year:</b>	2003
<b>Date Closed:</b>	05/12/2014	<b>Model Series:</b>	AJ
<b>Dealer Code:</b>	S165676	<b>Mileage:</b>	005672
<b>Dealer Name:</b>	Saturn of San Juan CSan Juan Capistrano	<b>Dealer State:</b>	CA
<b>Dealer Phone:</b>	9492485411	<b>Division:</b>	Saturn

---

SYMPTOM ABSTRACT— STALL ENGINE ENGINE STALL WHILE DRIVING INTERMITTE

RESOLUTION ABSTRACT-

UCC CODE 1-----

UCC-1 DESCRIPTION— Engine

UCC CODE 2-----

UCC-2 DESCRIPTION—

UCC CODE 3-----

UCC-3 DESCRIPTION—

11/25/2003 13:19:47 SBD Template - VOELLINGER

tech stated ENGINE STALL WHILE DRIVING INTERMITTENT.

no codes.

tech cannot duplicate.

tech stated the owner comments they will pull over, and restart the car

just fine.

DIAGNOSTICS:

tech checked battery cables.

load tested the battery.

no codes.

rec:

check G101 behind left headlight,

G103 engine compartment left side lower frame rail,

too heavy of a key chane causing ignition voltage loss,

loose connector or wires at ignition switch, etc.

11/25/2003 13:19:47 History - VOELLINGER

## ***TECHNICAL ASSISTANCE CENTER***

**\*\*\*\* GM RESTRICTED \*\*\*\***

<b><i>Case No:</i></b>	<b><i>06957025</i></b>	<b><i>VIN:</i></b>	<div><b>Privacy</b></div>
<b><i>Date Opened:</i></b>	<b><i>20031125</i></b>	<b><i>Model Year:</i></b>	<b><i>2003</i></b>
<b><i>Date Closed:</i></b>	<b><i>05/12/2014</i></b>	<b><i>Model Series:</i></b>	<b><i>AJ</i></b>
<b><i>Dealer Code:</i></b>	<b><i>S165676</i></b>	<b><i>Mileage:</i></b>	<b><i>005672</i></b>
<b><i>Dealer Name:</i></b>	<b><i>Saturn of San Juan CSan Juan Capistrano</i></b>	<b><i>Dealer State:</i></b>	<b><i>CA</i></b>
<b><i>Dealer Phone:</i></b>	<b><i>9492485411</i></b>	<b><i>Division:</i></b>	<b><i>Saturn</i></b>

---

***12/30/2003 11:26:45 KUBICHAR - Closing***

***Tech states he was unable to duplicate concern. Returned vehicle to customer. Closing.***